

To be filled by the Inspecting Officer

(Asst. Engineer)

1. Name of the Officer : Babu K Paul
2. Name of the School : VIDHYA VIHAR CENTRAL SCHOOL KAKKASSEY
(Run by vidhya vihar Educational & Charitable Trust)
3. Location with name of orphanage District; : CHAVAKKAD
4. Classification of Building as specified in column 4 of the application for fitness certificate and size : Main block ground floor 12394sq ft -1999
Toilet block ground floor 1038 sq.FT-1999
Main Block I Floor 12372sq.Ft-2000
Main Block II Floor 12066 sq.ft -2001
5. Period for which the certificate is issued :2021-2022
6. Nature of defects , if any
- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner :No major defects are noticed at the time of inspection
8. Whether maintenance works have been done properly : Yes
9. Whether the structure is found or not for conducting classes : Sound and structure safe under normal weather conditions

Note :

1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 22/07/21 and found to be fit / unfit to conduct classes, for the period. 2021-2022 for the reasons stated above.

Place : Chittattukkara

Date : 22/7/2021



(Seal)

BABU. K. PAUL

ASSISTANT ENGINEER

LOCA Assistant Engineer

PALAYALLY GRAMA PANCHAYATH

PRINCIPAL
Vidya Vihar Central School
Kakkassery, Chittattukkara-686511